

Caerbont Automotive Instruments

"The original makers of SMITHS Instruments"

Instructions for

Programmable Speedometer Electronic

Independently tested and approved to 95/54/EC

Designed and manufactured under ISO9001:2008 quality standard.

Caerbont Automotive Instruments Ltd Abercrave, Swansea, SA9 1SH

Fax: +44 (0) 1639 732201 Tel: +44 (0) 1639 732200

www.caigauge.com

Installation Guide

(x indicates any character in the part number) Part numbers: XES3 and XES5 -1bxx-xx Telemetrix and International range speedometers

Application Notes

powered and installed in the vehicle. button. This must be completed with the speedometer number of pulses per mile (or kilometre) generated by of operation is 10 to 16 volts, negative earth only. the speed sensor - this is achieved via the trip reset The speedometer must be calibrated to match the The operating voltage is nominally 12 volts. The range

The calibration range is from 1,000 to 120,000 pulses

Disconnect the negative battery cable prior to any installation Caution

Wire Colour Pin No. Connect to Green 1 Switched ignition positive 12volt supply (via 3A fuse) Brown/slate 2 Connected to trip reset switch Used only if speed sensor requires load resistance - see note below White/Red 4 Instrument illumination 12volt supply (side light feed) Black 5 Chassis or battery negative White/Black 6 Speed signal input from ECU or wire sensor Red/blue 7 Speed signal input for low voltage output 2 wire sensors (generally inductive) Light green/purple 8 Not used		Harı	Harness connections
n/slate 2 n/slate 2 n/slate 2 3 s/Black 6 youngle 7	Wire Colour	Pin No.	Connect to
//purple 8 N			
n/slate 2 a/Red 4 e/Red 4 e/Red 5 e/Black 6 e/Black 6	Green	7	Switched ignition positive 12volt supply (via 3A fuse)
3 // 4 // 5 // 5 // 5 // 5 // 5 // 6 // 6	Brown/slate	2	Connected to trip reset switch
e/Red 4 (5 e/Black 6 e/Black 7 e/purple 8	Red	ω	Used only if speed sensor requires load resistance - see note below
e/Black 6 olue 7 n/purple 8	White/Red	4	Instrument illumination 12volt supply (side light feed)
e/Black 6 olue 7 n/purple 8	Black	5	Chassis or battery negative
olue 7 N/purple 8	White/Black	6	Speed signal input from ECU or wire sensor
1/purple 8	Red/blue	7	Speed signal input for low voltage output 2 wire sensors (generally inductive)
	Light green/purple	00	Not used

some 3 wire sensors. Red wire connection is only required for

Connect to 0volts (chassis) for PNP types Connect to 12volts for NPN type sensors

distance travelled. same point. Move the vehicle forward by one complete wheel revolution and measure the closest point to the ground, mark the ground at the vehicle on a flat surface and mark the tyre at the wheels revolve per mile (or kilometre). Stand the Calculating The Calibration Number
You need to know the number of times your

distance travelled in inches Wheel revs per mile = 63360 divided by the

distance travelled in metres Wheel revs per km. = 1000 divided by the

per mile/km) To Calculate the Calibration Number (pulses

- moving past the sensor (eg. prop shaft mounting). For magnetic sensor, magnets or bolt heads
- Calibration number = (wheel revs per magnets or bolts). mile/km) x (diff ratio) x (number of
- wheel revolutions and count the number of cable Push vehicle forward on flat ground for 6 complete For sender driven from transmission cable drive.
- Cable turns per mile (or km) = (Wheel revolutions per mile + 6) x cable turns counted.
- mile (or km) x number of pulses per Calibration number = Cable turns per sender revolution.

Setting The Calibration – Inputting The Calibration Number / Pulses Per Unit Distance.

There are two methods to setting the calibration:

- (i) Manually inputting the PPU number.
- (ii) Using 'drive to set' facility.

The calibration mode is selected by switching on the ignition while simultaneously pressing the trip reset button. The pointer will travel to full scale and return to zero.

If the button is released before the pointer returns to zero, the manual setting procedure will be selected and the LCD (odo.) will read 'SET PPU'

If the button is released after the pointer returns to zero the 'drive to set' mode is selected and the LCD will show 'DTS PPU.'

At this point, pressing the reset button momentarily will toggle between 'SET PPU' and DTS PPU'

Manually Inputting The PPU Number

Set the LCD to display 'SET PPU' as described above.

Press the reset button for 2-3 seconds, the LCD will show the calibration number currently set. Each digit within the calibration number will flash in turn for approximately 2 seconds. When a digit is flashing, each depression of the reset button will increment the digit by one. Once the last (right-most) digit has been set/reset, the whole number will flash. Press the reset button and the LCD will display 'DONE.' After 3 seconds the LCD will display 'SET PPU,' the setting is now complete. Switch off the ignition.

Drive To Set PPU

Set the LCD to display 'DTS PPU' as described above.

Press the reset button for 2-3 seconds, the LCD will display '*00000.' Drive exactly one mile. While driving, the odometer will count the number of pulses generated by the sender. Press the reset button for 2-3 seconds, the LCD will display 'DONE.' Within a few seconds the LCD will return to the 'DTS PPU', display. The setting is now complete. Switch off the ignition.

IMPORTANT – When driving in 'drive to set' mode the speedometer will register but not accurately. The speedometer cannot be used on a public highway in this mode.